

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1554	6264	BN 6264	SD38P	H3 paint	Was re# to BNSF 1804 for a brief period of time.
1555	6266	BN 6266	SD38P	H3 paint	Was re# to BNSF 1806 for a brief period of time.
1556	6267	BN 6267	SD38P	BN paint	Was re# to BNSF 1807 for a brief period of time.
1557	6269	BN 6269	SD38P	BN paint	Was re# to BNSF 1809 for a brief period of time.
1558	6270	BN 6270	SD38P	BN paint	Was re# to BNSF 1810 for a brief period of time.
1559	6265	BN 6265	SD38P	H1 paint	Was re# to BNSF 1805 for a brief period of time.
1560	6268	BN 6268	SD38P	H3 paint	Was re# to BNSF 1808 for a brief period of time.
1561	6260	BN 6260	SD38P	BN paint	Was re# to BNSF 1800 for a brief period of time.
1562	6261	BN 6261	SD38P	H3 paint	Was re# to BNSF 1801 for a brief period of time.
1563	6262	BN 6262	SD38P	H3 paint	Was re# to BNSF 1802 for a brief period of time.
1564	6263	BN 6263	SD38P	H3 paint	Was re# to BNSF 1803 for a brief period of time.
1565	6485	ATSF 5835	SD40-2R	H3 paint	Was re# to BNSF 7950 for a brief period of time.
1566	6500	ATSF 5850	SD40-2R	H3 paint	Was re# to BNSF 7951 for a brief period of time.
1567	6458	ATSF 5808	SD40-2R	H3 paint	Was re# to BNSF 7953 for a brief period of time.
1568	6489	ATSF 5839	SD40-2R	H3 paint	Was re# to BNSF 7952 for a brief period of time.
1569	6509	ATSF 5860	SD40-2R	H3 paint	Was re# to BNSF 7954 for a brief period of time.
1570	6479	ATSF 5829	SD40-2R	H3 paint	Was re# to BNSF 7955 for a brief period of time.
1571	6492	ATSF 5842	SD40-2R	H3 paint	Was re# to BNSF 7956 for a brief period of time.
1572	6468	ATSF 5818	SD40-2R	H3 paint	
1573	6453	ATSF 5803	SD40-2R	H3 paint	
1574	6502	ATSF 5852	SD40-2R	H3 paint	
1575	6472	ATSF 5822	SD40-2R	H3 paint	
1576	7859	BN 7859	SD40-2	H1 paint	
1577					
1578					
1579					
1580					
1581					
1582					
1583					
1584					
1585					
1586					
1587					
1588					
1589					
1590					
1591	7885	BN 7885	SD40-2	H1 paint	
1592	7887	BN 7887	SD40-2	H1 paint	
1593	7888	BN 7888	SD40-2	H3 paint	
1594	7821	BN 7821	SD40-2	BN paint	
1595	7822	BN 7822	SD40-2	H3 paint	
1596	7823	BN 7823	SD40-2	H3 paint	
1597	7824	BN 7824	SD40-2	H3 paint	
1598	6717	ATSF 5058	SD40-2	H1 paint	

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1599	6718	ATSF 5059	SD40-2	H1 paint	
1600	1600	BN 1702	GP9	H1 paint	*Lettered "GN" instead of BNSF on the cab.
1600	6719	ATSF 5060	SD40-2	H1 paint	
1601	6720	ATSF 5061	SD40-2	H1 paint	
1602	6721	ATSF 5062	SD40-2	H1 paint	
1603	6722	ATSF 5063	SD40-2	ATSF paint	
1604	6723	ATSF 5064	SD40-2	ATSF paint	
1605	6724	ATSF 5065	SD40-2	ATSF paint	
1606	6725	ATSF 5066	SD40-2	H1 paint	
1607	6726	ATSF 5067	SD40-2	ATSF paint	
1608	6727	ATSF 5068	SD40-2	ATSF paint	
1609	6728	ATSF 5069	SD40-2	ATSF paint	
1610	6729	ATSF 5070	SD40-2	ATSF paint	
1611	6730	ATSF 5071	SD40-2	ATSF paint	
1612	6731	ATSF 5072	SD40-2	ATSF paint	
1613	6732	ATSF 5073	SD40-2	H1 paint	
1614	6733	ATSF 5074	SD40-2	ATSF paint	
1615	6734	ATSF 5075	SD40-2	H1 paint	
1616	6735	ATSF 5076	SD40-2	H1 paint	
1617	6736	ATSF 5077	SD40-2	ATSF paint	
1618	6737	ATSF 5078	SD40-2	ATSF paint	
1619	6738	ATSF 5079	SD40-2	H1 paint	
1620	6739	ATSF 5080	SD40-2	H3 paint	
1621	6740	ATSF 5081	SD40-2	ATSF paint	
1622	6741	ATSF 5082	SD40-2	ATSF paint	
1623	6742	ATSF 5083	SD40-2	H1 paint	
1624	6743	ATSF 5084	SD40-2	H1 paint	
1625	6744	ATSF 5085	SD40-2	H3 paint	
1626	6745	ATSF 5086	SD40-2	H1 paint	
1627	6746	ATSF 5087	SD40-2	ATSF paint	
1628	6747	ATSF 5088	SD40-2	H1 paint	
1629	6748	ATSF 5089	SD40-2	ATSF paint	
1630	6749	ATSF 5090	SD40-2	ATSF paint	
1631	6750	ATSF 5091	SD40-2	H1 paint	
1632	6751	ATSF 5092	SD40-2	H1 paint	
1633	6752	ATSF 5093	SD40-2	H3 paint	
1634	6753	ATSF 5094	SD40-2	H1 paint	
1635	6754	ATSF 5095	SD40-2	H3 paint	
1636	6755	ATSF 5096	SD40-2	ATSF paint	
1637	6756	ATSF 5097	SD40-2	H1 paint	
1638	6757	ATSF 5098	SD40-2	ATSF paint	
1639	6758	ATSF 5099	SD40-2	H1 paint	
1640	6759	ATSF 5100	SD40-2	ATSF paint	
1641	6760	ATSF 5101	SD40-2	H3 paint	
1642	6761	ATSF 5102	SD40-2	H1 paint	

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1643	6762	ATSF 5103	SD40-2	H1 paint	
1644	6763	ATSF 5104	SD40-2	ATSF paint	
1645	6764	ATSF 5105	SD40-2	ATSF paint	
1646	6765	ATSF 5106	SD40-2	H1 paint	
1647	6766	ATSF 5107	SD40-2	ATSF paint	
1648	6767	ATSF 5108	SD40-2	ATSF paint	
1649	6783	BN 6783	SD40-2	H1 paint	
1650					
1651	6851	BN 6851	SD40-2	BN paint	
1652	7054	BN 7054	SD40-2	BN paint	
1653	7055	BN 7055	SD40-2	BN paint	
1654	7056	BN 7056	SD40-2	BN paint	
1655	7057	BN 7057	SD40-2	H3 paint	
1656	7058	BN 7058	SD40-2	BN paint	
1657	7059	BN 7059	SD40-2	BN paint	
1658	7060	BN 7060	SD40-2	BN paint	
1659	7061	BN 7061	SD40-2	BN paint	
1660	7062	BN 7062	SD40-2	BN paint	
1661	8010	BN 8010	SD40-2	H1 paint	
1662	8011	BN 8011	SD40-2	BN paint	
1663	8012	BN 8012	SD40-2	BN paint	
1664	8013	BN 8013	SD40-2	H1 paint	
1665	8014	BN 8014	SD40-2	H1 paint	
1666	8015	BN 8015	SD40-2	H3 paint	
1667	8016	BN 8016	SD40-2	H1 paint	
1668	8017	BN 8017	SD40-2	H1 paint	
1669	8018	BN 8018	SD40-2	H1 paint	
1670	8019	BN 8019	SD40-2	BN paint	
1671	8020	BN 8020	SD40-2	BN paint	
1672	8022	BN 8022	SD40-2	H1 paint	
1673	8023	BN 8023	SD40-2	BN paint	
1674	8024	BN 8024	SD40-2	BN paint	
1675	8025	BN 8025	SD40-2	BN paint	
1676	8026	BN 8026	SD40-2	H1 paint	
1677	8027	BN 8027	SD40-2	H1 paint	
1678	8028	BN 8028	SD40-2	BN paint	
1679	8029	BN 8029	SD40-2	H1 paint	
1680	6807	BN 6807	SD40-2	BN paint	
1681	6808	BN 6808	SD40-2	H1 paint	
1682	6809	BN 6809	SD40-2	H1 paint	
1683	6810	BN 6810	SD40-2	H1 paint	
1684	6813	BN 6813	SD40-2	H1 paint	
1685	6814	BN 6814	SD40-2	BN paint	
1686	6815	BN 6815	SD40-2	BN paint	
1687	6816	BN 6816	SD40-2	BN paint	

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1688	6817	BN 6817	SD40-2	H1 paint	
1689	6818	BN 6818	SD40-2	BN paint	
1690	6819	BN 6819	SD40-2	H1 paint	
1691	6820	BN 6820	SD40-2	H1 paint	Wrecked...waiting to be repaired
1692	6821	BN 6821	SD40-2	H3 paint	
1693	6822	BN 6822	SD40-2	BN paint	
1694	6823	BN 6823	SD40-2	H1 paint	
1695	6848	BN 6805	SD40-2	H1 paint	
1696	6849	BN 6806	SD40-2	BN paint	
1697	6906	BN 6907	SD40-2	BN paint	
1698	6907	BN 6906	SD40-2	H1 paint	
1699	BN 6908	BN 6908	SD40-2	BN paint	
1700	6909	BN 6902	SD40-2	H1 paint	
1701	6910	BN 6910	SD40-2	BN paint	
1702	6911	BN 6911	SD40-2	H1 paint	
1703	6914	BN 6903	SD40-2	BN paint	
1704	6921	BN 6904	SD40-2	H1 paint	
1705	6812	BN 6801	SD40-2	H1 paint	
1706	6837	BN 6802	SD40-2	BN paint	
1707	6838	BN 6803	SD40-2	BN paint	
1708	6839	BN 6804	SD40-2	H3 paint	
1709	6869	ATSF 5141	SD40-2	H3 paint	
1710	6870	ATSF 5142	SD40-2	H1 paint	
1711	6871	ATSF 5143	SD40-2	H3 paint	
1712	6872	ATSF 5144	SD40-2	H1 paint	
1713	6873	ATSF 5145	SD40-2	H3 paint	
1714	6874	ATSF 5146	SD40-2	ATSF paint	
1715	6875	ATSF 5147	SD40-2	H1 paint	
1716	6876	ATSF 5148	SD40-2	H3 paint	
1717	6877	ATSF 5149	SD40-2	H1 paint	
1718	6878	ATSF 5150	SD40-2	H1 paint	
1719	6879	ATSF 5151	SD40-2	H3 paint	
1720	6880	ATSF 5152	SD40-2	H1 paint	
1721	6881	ATSF 5153	SD40-2	ATSF paint	
1722	6882	ATSF 5154	SD40-2	H3 paint	
1723	6883	ATSF 5155	SD40-2	ATSF paint	Was re# to BNSF 1613 from Dec 2010' to March 2011
1724	6884	ATSF 5156	SD40-2	H1 paint	
1725	6885	ATSF 5157	SD40-2	H3 paint	
1726	6886	ATSF 5158	SD40-2	H1 paint	
1727	6887	ATSF 5159	SD40-2	H3 paint	
1728	6888	ATSF 5160	SD40-2	H1 paint	
1729	6889	ATSF 5161	SD40-2	H1 paint	
1730	6890	ATSF 5162	SD40-2	H3 paint	
1731	6891	ATSF 5163	SD40-2	H1 paint	
1732	6892	ATSF 5164	SD40-2	H3 paint	

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1733	6893	ATSF 5165	SD40-2	H3 paint	
1734	6894	ATSF 5166	SD40-2	H3 paint	
1735	6895	ATSF 5167	SD40-2	H3 paint	
1736	6896	ATSF 5168	SD40-2	H3 paint	
1737	6897	ATSF 5169	SD40-2	H3 paint	
1738	6898	ATSF 5170	SD40-2	ATSF paint	
1739	6899	ATSF 5171	SD40-2	ATSF paint	
1740	6900	ATSF 5172	SD40-2	ATSF paint	
1741	6901	ATSF 5173	SD40-2	ATSF paint	
1742	6902	ATSF 5174	SD40-2	H3 paint	
1743	6903	ATSF 5175	SD40-2	H3 paint	
1744	6904	ATSF 5176	SD40-2	H1 paint	
1745	6905	ATSF 5177	SD40-2	H1 paint	
1746	6930	ATSF 5178	SD40-2	ATSF paint	
1747	6931	ATSF 5179	SD40-2	ATSF paint	
1748	6932	ATSF 5180	SD40-2	H3 paint	
1749	6933	ATSF 5181	SD40-2	H3 paint	
1750	6934	ATSF 5182	SD40-2	H1 paint	
1751	6935	ATSF 5183	SD40-2	ATSF paint	
1752	6936	ATSF 5184	SD40-2	H1 paint	Was re# to BNSF 1617 from Nov 2010 to June 2011
1753	6937	ATSF 5185	SD40-2	H1 paint	
1754	6938	ATSF 5186	SD40-2	H1 paint	
1755	6939	ATSF 5187	SD40-2	ATSF paint	
1756	6940	ATSF 5188	SD40-2	H1 paint	
1757	6941	ATSF 5189	SD40-2	ATSF paint	
1758	6942	ATSF 5190	SD40-2	ATSF paint	
1759	6943	ATSF 5191	SD40-2	H1 paint	
1760	6944	ATSF 5192	SD40-2	ATSF paint	
1761	6945	ATSF 5200	SD40-2	ATSF paint	
1762	6946	ATSF 5201	SD40-2	H1 paint	
1763	6947	ATSF 5202	SD40-2	H1 paint	
1764	6948	ATSF 5203	SD40-2	H1 paint	
1765	6949	ATSF 5204	SD40-2	ATSF paint	
1766	6950	ATSF 5205	SD40-2	H1 paint	
1767	6951	ATSF 5206	SD40-2	ATSF paint	
1768	6952	ATSF 5207	SD40-2	H1 paint	
1769	6954	ATSF 5209	SD40-2	H1 paint	
1770	6955	ATSF 5210	SD40-2	ATSF paint	
1771	6956	ATSF 5211	SD40-2	H1 paint	
1772	6957	ATSF 5212	SD40-2	ATSF paint	
1773	6958	ATSF 5213	SD40-2	ATSF paint	
1774	7029	BN 7029	SD40-2	BN paint	
1775	7030	BN 7030	SD40-2	BN paint	
1776	7031	BN 7031	SD40-2	H1 paint	
1777	7032	BN 7032	SD40-2	BN paint	

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1778	7033	BN 7033	SD40-2	H1 paint	
1779	7034	BN 7034	SD40-2	BN paint	
1780	7035	BN 7035	SD40-2	H1 paint	
1781	7036	BN 7036	SD40-2	BN paint	
1782	7037	BN 7037	SD40-2	BN paint	
1783	7038	BN 7038	SD40-2	BN paint	
1784	7039	BN 7039	SD40-2	BN paint	
1785	7040	BN 7040	SD40-2	H1 paint	
1786	7041	BN 7041	SD40-2	BN paint	
1787	7042	BN 7042	SD40-2	BN paint	
1788	7044	BN 7044	SD40-2	BN paint	
1789	7045	BN 7045	SD40-2	BN paint	
1790	7046	BN 7046	SD40-2	BN paint	
1791	7047	BN 7047	SD40-2	H1 paint	
1792	7048	BN 7048	SD40-2	BN paint	
1793	8112	BN 8112	SD40-2	H1 paint	Was re# to BNSF 8090 from 2002-2007.
1794	8167	BN 8167	SD40-2	H3 paint	Was re# to BNSF 8091 from 2002-2007.
1795	7825	BN 7825	SD40-2	BN paint	
1796	7826	BN 7826	SD40-2	H3 paint	
1797	7827	BN 7827	SD40-2	H3 paint	
1798	7828	BN 7828	SD40-2	BN paint	
1799	6344	ATSF 5029	SD40-2	H3 paint	
1800	6345	ATSF 5030	SD40-2	H3 paint	
1801	6346	ATSF 5031	SD40-2	H1 paint	
1802	6347	ATSF 5032	SD40-2	ATSF paint	
1803	6348	ATSF 5033	SD40-2	H3 paint	
1804	6349	ATSF 5034	SD40-2	H1 paint	
1805	6350	ATSF 5035	SD40-2	H3 paint	
1806					
1807	6352	ATSF 5038	SD40-2	H3 paint	
1808	6353	ATSF 5039	SD40-2	H3 paint	
1809	6354	ATSF 5040	SD40-2	ATSF paint	
1810	6355	ATSF 5041	SD40-2	H3 paint	
1811	6356	ATSF 5042	SD40-2	H3 paint	
1812	6357	ATSF 5043	SD40-2	H3 paint	
1813	6358	ATSF 5044	SD40-2	H3 paint	
1814	6359	ATSF 5045	SD40-2	H3 paint	
1815	6360	ATSF 5046	SD40-2	H3 paint	
1816	6361	ATSF 5047	SD40-2	H3 paint	
1817	6708	ATSF 5049	SD40-2	H3 paint	
1818	6709	ATSF 5050	SD40-2	H3 paint	
1819	6710	ATSF 5051	SD40-2	H3 paint	
1820	6711	ATSF 5052	SD40-2	H3 paint	
1821	6712	ATSF 5053	SD40-2	H3 paint	
1822	6713	ATSF 5054	SD40-2	H3 paint	

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1823	6714	ATSF 5055	SD40-2	H3 paint	
1824	6715	ATSF 5056	SD40-2	H3 paint	
1825	6716	ATSF 5057	SD40-2	H3 paint	
1826	6378	BN 6378	SD40-2	H1 paint	
1827	7815	BN 7815	SD40-2	BN paint	
1828	6380	BN 6380	SD40-2	BN paint	
1829	6381	BN 6381	SD40-2	BN paint	
1830	6382	BN 6382	SD40-2	BN paint	
1831	6383	BN 6383	SD40-2	BN paint	
1832	6384	BN 6384	SD40-2	BN paint	
1833	6700	BN 6700	SD40-2	H1 paint	
1834	6701	BN 6701	SD40-2	H1 paint	
1835	6702	BN 6702	SD40-2	BN paint	
1836	6703	BN 6703	SD40-2	BN paint	
1837	6704	BN 6704	SD40-2	BN paint	
1838	6705	BN 6705	SD40-2	H1 paint	
1839	6706	BN 6706	SD40-2	BN paint	
1840	6707	BN 6707	SD40-2	BN paint	
1841	6917	BN 6917	SD40-2	BN paint	
1842	6918	BN 6918	SD40-2	H1 paint	
1843	6919	BN 6919	SD40-2	H1 paint	
1844	6920	BN 6920	SD40-2	H1 paint	
1845	6923	BN 6923	SD40-2	BN paint	
1846	6924	BN 6924	SD40-2	BN paint	
1847	6925	BN 6925	SD40-2	H1 paint	
1848	6926	BN 6926	SD40-2	BN paint	
1849	6927	BN 6927	SD40-2	BN paint	
1850	6824	BN 6824	SD40-2	H3 paint	
1851	6825	BN 6825	SD40-2	H3 paint	
1852	6826	BN 6826	SD40-2	H3 paint	
1853	6828	BN 6828	SD40-2	H1 paint	
1854	6829	BN 6829	SD40-2	H3 paint	
1855	6830	BN 6830	SD40-2	H1 paint	
1856	6831	BN 6831	SD40-2	H3 paint	
1857	6832	BN 6832	SD40-2	H1 paint	
1858	6833	BN 6833	SD40-2	H1 paint	
1859	6835	BN 6835	SD40-2	H3 paint	
1860	6836	BN 6836	SD40-2	H3 paint	
1861	6928	BN 6928	SD40-2	BN paint	
1862	7152	BN 7152	SD40-2	H1 paint	
1863	7136	BN 7136	SD40-2	H1 paint	
1864	7150	BN 7150	SD40-2	H1 paint	
1865	7185	BN 7185	SD40-2	H1 paint	
1866	7184	BN 7184	SD40-2	H1 paint	
1867	7870	BN 7870	SD40-2	H1 paint	

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1868	7809	BN 7809	SD40-2	BN paint	
1869	6773	BN 6773	SD40-2	BN paint	
1870	7810	BN 7810	SD40-2	BN paint	
1871	6335	ATSF 5020	SD40-2	ATSF paint	
1872	6339	ATSF 5024	SD40-2	H1 paint	
1873	6341	ATSF 5026	SD40-2	H1 paint	
1874	6342	ATSF 5027	SD40-2	ATSF paint	
1875	6336	ATSF 5021	SD40-2	ATSF paint	
1876	6338	ATSF 5023	SD40-2	H3 paint	
1877	6340	ATSF 5025	SD40-2	H3 paint	
1878	6337	ATSF 5022	SD40-2	H3 paint	
1879	6768	ATSF 5109	SD40-2	H3 paint	
1880	6770	ATSF 5111	SD40-2	ATSF paint	
1881	6772	ATSF 5113	SD40-2	H1 paint	
1882	6799	ATSF 5115	SD40-2	H3 paint	
1883	6801	ATSF 5117	SD40-2	H3 paint	
1884	6803	ATSF 5119	SD40-2	H3 paint	
1885	6805	ATSF 5121	SD40-2	ATSF paint	
1886	6852	ATSF 5123	SD40-2	ATSF paint	
1887	6769	ATSF 5110	SD40-2	H3 paint	
1888	6771	ATSF 5112	SD40-2	H3 paint	
1889	6798	ATSF 5114	SD40-2	H1 paint	
1890	6800	ATSF 5116	SD40-2	H1 paint	
1891	6802	ATSF 5118	SD40-2	H3 paint	
1892	6804	ATSF 5120	SD40-2	H1 paint	
1893	6806	ATSF 5122	SD40-2	H3 paint	
1894	6853	ATSF 5124	SD40-2	H3 paint	
1895	6867	ATSF 5139	SD40-2	H3 paint	
1896	6856	ATSF 5127	SD40-2	H3 paint	
1897	6858	ATSF 5129	SD40-2	H3 paint	
1898	6860	ATSF 5131	SD40-2	H1 paint	
1899	6862	ATSF 5133	SD40-2	H3 paint	
1900	6864	ATSF 5135	SD40-2	H3 paint	
1901	6866	ATSF 5137	SD40-2	H3 paint	
1902	6854	ATSF 5125	SD40-2	H3 paint	
1903	6855	ATSF 5126	SD40-2	ATSF paint	
1904	6861	ATSF 5132	SD40-2	H3 paint	
1905	6857	ATSF 5128	SD40-2	H1 paint	
1906	6863	ATSF 5134	SD40-2	H3 paint	
1907	6859	ATSF 5130	SD40-2	H1 paint	
1908	6865	ATSF 5136	SD40-2	H3 paint	
1909	6868	ATSF 5140	SD40-2	H3 paint	
1910	6329	BN 6328	SD40-2	H1 paint	
1910 (GN)	6200	ATSF 1556	SD39	ATSF paint	
1911	6330	BN 6329	SD40-2	H1 paint	

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1911 (GN)	6201	ATSF 1557	SD39	ATSF paint	
1912	6331	BN 6331	SD40-2	BN paint	
1912 (GN)	6202	ATSF	SD39	ATSF paint	Retired.
1913	6332	BN 6332	SD40-2	BN paint	
1913 (GN)	6203	ATSF 1559	SD39	ATSF paint	
1914	6333	BN 6333	SD40-2	BN paint	
1914 (GN)	6204	ATSF 1560	SD39	H1 paint	Retired.
1915	6334	BN 6334	SD40-2	BN paint	
1915 (GN)	6205	ATSF 1561	SD39	ATSF paint	
1916	6397	BN 6325	SD40-2	BN paint	
1916 (GN)	6206	ATSF	SD39	ATSF paint	Retired.
1917					
1917 (GN)	6207	ATSF 1563	SD39	H1 paint	Retired.
1918	6399	BN 6327	SD40-2	H1 paint	
1918 (GN)	6208	ATSF	SD39	H3 paint	
1919	6912	BN 6912	SD40-2	H1 paint	
1919 (GN)	6209	ATSF 1565	SD39	ATSF paint	Retired.
1920	6913	BN 6913	SD40-2	BN paint	
1920 (GN)	6210	ATSF 1566	SD39	H1 paint	Retired.
1921	6915	BN 6915	SD40-2	H1 paint	
1921 (GN)	6211	ATSF 1567	SD39	ATSF paint	
1922	6916	BN 6916	SD40-2	BN paint	
1922 (GN)	6212	ATSF 1568	SD39	H1 paint	Retired.
1923	6343	ATSF 5028	SD40-2	ATSF paint	
1923 (GN)	6213	ATSF 1569	SD39	ATSF paint	
1924	6362	ATSF	SD40-2	H1 paint	
1924 (GN)	6214	ATSF	SD39	ATSF paint	Retired.
1925	7126	BN 7126	SD40-2	H1 paint	
1925 (GN)	6215	ATSF 1571	SD39	ATSF paint	Retired.
1926	7154	BN 7154	SD40-2	H1 paint	
1926 (GN)	6216	ATSF 1572	SD39	H3 paint	Retired.
1927	7128	BN 7128	SD40-2	BN paint	
1927 (GN)	6217	ATSF	SD39	ATSF paint	Retired.
1928	7129	BN 7129	SD40-2	H3 paint	
1928 (GN)	6218	ATSF 1574	SD39	ATSF paint	Retired.
1929	7130	BN 7130	SD40-2	H1 paint	
1929 (GN)	6219	ATSF 1575	SD39	ATSF paint	
1930	7131	BN 7131	SD40-2	H1 paint	
1931	7132	BN 7132	SD40-2	H1 paint	
1932	7133	BN 7133	SD40-2	BN paint	
1933	7134	BN 7134	SD40-2	BN paint	
1934	7135	BN 7135	SD40-2	H1 paint	
1935	7137	BN 7137	SD40-2	BN paint	
1936	7138	BN 7138	SD40-2	H3 paint	
1937	7139	BN 7139	SD40-2	BN paint	

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1938	7140	BN 7140	SD40-2	H3 paint	
1939	7141	BN 7141	SD40-2	H1 paint	
1940	7142	BN 7142	SD40-2	BN paint	
1941	7143	BN 7143	SD40-2	H1 paint	
1942	7883	BN 7883	SD40-2	H1 paint	
1943	7145	BN 7145	SD40-2	BN paint	
1944	7146	BN 7146	SD40-2	H1 paint	
1945	7147	BN 7147	SD40-2	BN paint	
1946	7148	BN 7148	SD40-2	H1 paint	
1947	7151	BN 7151	SD40-2	BN paint	
1948	7153	BN 7153	SD40-2	BN paint	
1949	7127	BN 7127	SD40-2	H1 paint	
1950	7155	BN 7155	SD40-2	H1 paint	
1951	7157	BN 7157	SD40-2	BN paint	
1952	6363	BN 6363	SD40-2	BN paint	
1953	6364	BN 6364	SD40-2	BN paint	
1954	6365	BN 6365	SD40-2	H1 paint	
1955	6374	BN 6348	SD40-2	BN paint	
1956	6375	BN 6349	SD40-2	H1 paint	
1957	6376	BN 6350	SD40-2	H1 paint	
1958	6377	BN 6351	SD40-2	BN paint	
1959	6386	BN 6352	SD40-2	BN paint	
1960	6387	BN 6353	SD40-2	BN paint	
1961	6388	BN 6354	SD40-2	BN paint	
1962	6389	BN 6355	SD40-2	BN paint	
1963	6390	BN 6356	SD40-2	H1 paint	
1964	6391	BN 6357	SD40-2	BN paint	
1965	6392	BN 6358	SD40-2	H1 paint	
1966	6393	BN 6359	SD40-2	BN paint	
1967	6394	BN 6360	SD40-2	H1 paint	
1968	6395	BN 6361	SD40-2	BN paint	
1969	6396	BN 6362	SD40-2	BN paint	
1970	6366	BN 6366	SD40-2	H1 paint	
1971	6368	BN 6368	SD40-2	H3 paint	
1972	6369	BN 6369	SD40-2	BN paint	
1973	6370	BN 6370	SD40-2	BN paint	
1974	6371	BN 6371	SD40-2	H1 paint	
1975	6372	BN 6372	SD40-2	H1 paint	
1976	6373	BN 6373	SD40-2	BN paint	
1977	6850	BN 6850	SD40-2	H1 paint	
1978	6929	BN 6950	SD40-2	H1 paint	
1979	7158	BN 7158	SD40-2	BN paint	
1980	7160	BN 7160	SD40-2	BN paint	
1981	7871	BN 7871	SD40-2	BN paint	
1982	7872	BN 7872	SD40-2	H1 paint	

The following information was compiled by Marlin Thorman. If you find any discrepancies or additions you can contact him at westbnsf@gmail.com

Current BNSF #	Previous BNSF #	BN/ATSF #	Type	Paint	Notes
1983	7873	BN 7873	SD40-2	H3 paint	
1984	7875	BN 7875	SD40-2	H1 paint	
1985	7876	BN 7876	SD40-2	BN paint	
1986	7877	BN 7877	SD40-2	H1 paint	
1987	7878	BN 7878	SD40-2	BN paint	
1988	7879	BN 7879	SD40-2	H1 paint	
1989	7880	BN 7880	SD40-2	H1 paint	
1990	7881	BN 7881	SD40-2	BN paint	
1991	7882	BN 7882	SD40-2	BN paint	
1992	7874	BN 7874	SD40-2	BN paint	
1993	7884	BN 7884	SD40-2	BN paint	
1994	7049	BN 7049	SD40-2	BN paint	
1995	7050	BN 7050	SD40-2	BN paint	
1996	7051	BN 7051	SD40-2	BN paint	
1997	7052	BN 7052	SD40-2	BN paint	
1998	7053	BN 7053	SD40-2	H1 paint	
1999	8064	BN 8064	SD40-2	H1 paint	